



WWW.GENERALCNC.CA

MANUALS

Changing from General CNC Operating Screen to Mach 3 Operating Screen

The following outlines the procedure to change the operating screen from General CNC to Mach 3:

1. Move your cursor over the word “by” in Powered by Gorilla CNC. Once the hand appears click and the menu bar should appear at the top of the screen.
2. Select “View” from the menu bar
3. Select “Load Screens”
4. Select the file “1024.set”
5. Move your cursor over the word “by” in Built by General and this will allow you to hide the menu bar.